UNIFORM HAZARDOUS WASTE MANIFEST 1. Generator's US EPA ID C. A.D. 0.846.45.	Docu	anifest ment No 0 9 3		THE RESERVE OF THE PROPERTY OF	nnvernous de le cestidade	ne shaded areas by Federal law.
Generator's Name and Mailing Address CDonnell Douglas Aircraft Co. 9503 S. Normandie Avenue	A. State Manifest Document Number 89476933					
orrance, CA 90502 Generator's Phone 213) 533-6677 K. L. Ander	son 722 M/S CE	-10		te Generator's IC A_H_Q_3_(5-6-9-8
5. Transporter 1 Company Name 6.	US EPA ID Number			te Transporter's		<u> 392/</u> 3)268-3137
J.C.I. Environmental Services IC.A. Transporter 2 Company Name 8.	D.10.15.18.10.11.18. US EPA ID Number	34041	E. Sta	te Transporter's	ID OIL	<u> </u>
Designated Facility Name and Site Address 10.	US EPA ID Number	<u> </u>		te Facility's ID		
ISPCI Lone Mountain Facility J.S. Pollution Control, Inc.		1	H. Fac	l ility's Phone	11	
<u> </u>	<u>ID.IO.I6.I5.I4.I3.I8.</u>	3.17.16 12. Cont		(405)69 13. Total	14.	I. Waste No.
1. US DOT Description (Including Proper Shipping Name, Hazard Class	s, and ID Number)	No.	Type	Quantity	Unit Wt/Vo	
Maste Sodium Hydroxide solution, Cor (D002) (RQ 1.000 lbs.)	rosive, UN1824			330		EPA/Other
b.		0 10 11	TI	OIŞIGICI		NOO2 State
		111	1			EPA/Other
C	A service of the serv					State EPA/Other
		111	1	1111		State
d						EPA/Other
J. Additional Descriptions for Materials Listed Above	Sw 33	1.20	K. Ha	andling Codes fo	r Wastes I	Listed Above
Daco 4-L Aluminum Milling Solution, p	H>12.5				d.	
Sadium Hudrovide 5-17% - Dodlum (Aluminate Z-D&					
Sodium Sülfide 2-4% Water =	Aluminate z-ba Remainder		C.			2011 1
Sodium Sülfide 2-4% Mater = USPCI ID# I M89-0866-89 Okl. Maste P 15. Special Handling Instructions and Additional Information	Ajuminate 2-3& Remainder <u>Ian # 96021 ⁵~</u>	133680				
Sodium Sulfide 2-4% Mater = USPCI TD# I M89-0866-89 Okl. Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling.	Aluminate 2-5& Remainder Lan # 96021 5~ PROF	/37670 ILE #2	2417			
Sodium Sülfide 2-4% Mater = USPCI ID# I M89-0866-89 Okl. Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. Tk-207	Aluminate 2-5% Remainder Ian # 96021 ^{Se} PROF HAUL	133680 ILE #2 ER 12	2417 234			
Sodium Sulfide 2-4% Nater = USPCI TD4 MA9-0866-89 Okl Naste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. TL207 16. GENERATOR'S CERTIFICATION: I hereby declare that the conteand are classified, preculations.	PROF HAUL SI Han sof this consignment arapects in proper condition for the constant of the constant of the condition for	ILE #2 ER 1 2 TE 1 2 e fully and a or transport	2417 234			
Sodium Sülfide 2-4% Nater = ISPCI TOA I MR9-0866-89 Obj. Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. GENERATOR'S CERTIFICATION: I hereby declare that the conte and are classified, packed, marked, and labeled, and are in all resultant government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practical process and the additional formation of the evironment. O	PROF HAUL Place to reduce the volum cable method of treatments.	ER 12 ER 12 e fully and a cor transport storage, on ienerator, I	2417 23417 23417 Accurated by high	ste generated to	the degre	ee I have determined which minimizes the
Sodium Sulfide 2-4% Nater = 15 Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. TL207 16. GENERATOR'S CERTIFICATION: I hereby declare that the contant and are classified, packed, marked, and labeled, and are in all resolutional government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practical present and future threat to human health and the environment. Of generation and select the best waste management method that is	PROF HAUL Place to reduce the volum cable method of treatments.	ER 12 ER 12 e fully and a cor transport storage, on ienerator, I	2417 23417 23417 Accurated by high	ste generated to	the degre	ee I have determined which minimizes the
Sodium Sulfide 2-4% Nater = 15 Special Handling Instructions and Additional Information Guide 60. Use proper protective clothing when handeling. Return to MDC if rejected. GENERATOR'S CERTIFICATION: I hereby declare that the conte and are classified, packed, marked, and labeled, and are in all restational government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practical present and future threat to human health and the environment, or generation and select the best waste management method that is Printed/Typed Name Kris L. Anderson Agent for M.D.A.C.	PROF HAUL ents of this consignment are spects in proper condition for cable method of treatment, R, if I am a small quantity gavailable to me and that I	ER 12 ER 12 e fully and a cor transport storage, on ienerator, I	2417 23417 23417 Accurated by high	ste generated to	the degre	ee I have determined which minimizes the inimize my waste
Sodium Sülfide 2-4% Nater = ISPCI TO# I M89-0866-89 Obl. Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. Theory 16. GENERATOR'S CERTIFICATION: I hereby declare that the conteand are classified, packed, marked, and labeled, and are in all resolutional government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practice present and future threat to human health and the environment, Organization and select the best waste management method that is Printed/Typed Name Kris L. Anderson Agent for M.D.A.C. 17. Transporter 1 Acknowledgement of Receipt of Materials	PROF HAUL SI ents of this consignment arrapects in proper condition for place to reduce the volum cable method of treatment, R, if I am a small quantity of available to me and that I	ER 12 ER 12 e fully and a or transport e and toxic storage, or lenerator, I can afford.	2417 234 ccuratel by high tity of was r dispose have ma	ste generated to al currently availa de à good faith	the degre	ee I have determined which minimizes the inimize my waste
Sodium Sülfide 2-4% Nater = ISPCI TO# I M89-0866-89 Obl. Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. Theory 16. GENERATOR'S CERTIFICATION: I hereby declare that the conteand are classified, packed, marked, and labeled, and are in all resolutional government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practice present and future threat to human health and the environment, Organization and select the best waste management method that is Printed/Typed Name Kris L. Anderson Agent for M.D.A.C. 17. Transporter 1 Acknowledgement of Receipt of Materials	PROF HAUL SI Parts of this consignment are spects in proper condition for place to reduce the volumicable method of treatment, R, if I am a small quantity gavailable to me and that I	ER 12 ER 12 e fully and a or transport e and toxic storage, or tenerator, I can afford.	2417 234 ccuratel by high tity of was r dispose have ma	ste generated to al currently availa de à good faith	the degre	Month Day Ye Month Day Ye Month Day Ye Month Day Ye
Sodium Sülfide 2-4% Nater = ISPCI TO# I M89-0866-89 OLL Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. Theory 16. GENERATOR'S CERTIFICATION: I hereby declare that the conteand are classified, packed, marked, and labeled, and are in all resonational government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practice present and future threat to human health and the environment; Of generation and select the best waste management method that is Printed/Typed Name Kris L. Anderson Agent for M.D.A.C. Printed/Typed Name CARLOS RODRIGUEZ	PROF HAUL SI ents of this consignment arrapects in proper condition for place to reduce the volum cable method of treatment, R, if I am a small quantity of available to me and that I	ER 12 ER 12 e fully and a or transport e and toxic storage, or lenerator, I can afford.	2417 234 ccuratel by high tity of was r dispose have ma	ste generated to al currently availa de à good faith	the degre	Month Day Ye Month Day Ye Month Day Ye
Sodium Sülfide 2-4% Nater = ISPCI TO# I M89-0866-89 OLL Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. TL-207 16. GENERATOR'S CERTIFICATION: I hereby declare that the content and are classified, packed, marked, and labeled, and are in all resolutional government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practice present and future threat to human health and the environment; Of generation and select the best waste management method that is Printed/Typed Name CARLOS ROBRIGUEZ 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name CARLOS ROBRIGUEZ 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	PROF HAUL PROF HAUL SI Prof HAUL SI Prof HAUL SI Prof HAUL SI Prof Prof HAUL SI Prof Prof Prof HAUL SI Prof	ER 12 ER 12 e fully and a cor transport e and toxic storage, or increasion. I can afford.	2417 234 ccuratel by high tity of was r dispose have ma	ste generated to al currently availa de à good faith	the degre	Month Day Ye Month Day Ye Month Day Ye Month Day Ye
Sodium Sülfide 2-4% Nater = ISPCI TO I MA9-0866-89 OLL Maste P 15. Special Handling Instructions and Additional Information Guide 160. Use proper protective clothing when handeling. Return to MDC if rejected. GENERATOR'S CERTIFICATION: I hereby declare that the conteand are classified, packed, marked, and labeled, and are in all resolutional government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practic present and future threat to human health and the environment; O generation and select the best waste management method that is Printed/Typed Name CARLOS ROBRIGUEZ 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name CARLOS ROBRIGUEZ 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	PROF HAUL PROF HAUL SI Prof HAUL SI Prof HAUL SI Prof HAUL SI Prof Prof HAUL SI Prof Prof Prof HAUL SI Prof	ER 12 ER 12 e fully and a cor transport e and toxic storage, or increasion. I can afford.	2417 234 ccuratel by high tity of was r dispose have ma	ste generated to al currently availa de à good faith	the degre	Month Day Ye Month Day Ye Month Day Ye Month Day Ye
Sodium Sülfide 2-4% Nater = ISPCI TO# I M89-0866-89 OLL Waste P 15. Special Handling Instructions and Additional Information Guide # 60. Use proper protective clothing when handeling. Return to MDC if rejected. TL-207 16. GENERATOR'S CERTIFICATION: I hereby declare that the content and are classified, packed, marked, and labeled, and are in all resolutional government regulations. If I am a large quantity generator, I certify that I have a program in to be economically practicable and that I have selected the practice present and future threat to human health and the environment; Of generation and select the best waste management method that is Printed/Typed Name CARLOS ROBRIGUEZ 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name CARLOS ROBRIGUEZ 18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	PROF HAUL SI The sents of this consignment are spects in proper condition for place to reduce the volum cable method of treatments, if I am a small quantity available to me and that I Signature Signature Signature Signature Signature	ER 12 ER 12 e fully and a or transport e and toxic storage, or increasers. I can afford.	2417 234 Cocurated by high- ity of was a dispose have man	ste generated to al currently availa de à good faith	the degre	Month Day Ye Month Day Ye Month Day Ye Month Day Ye

Yellow: TSDF SENDS THIS COPY TO GENERATOR WITHIN 30 DAYS

UNIFORM HAZARDOUS WASTE MANIFEST 1. Generator's US C.4A.D.40.48	S EPA ID No Ma	anifest ment No				ne shaded areas by Federal law.			
Generator's Name and Mailing Address Colonnel I Douglas Aircraft Co. 19503 S. Normandie Avenue				te Manifest Docu 897 te Generator's ID	176	ber 933			
Terrance, CA 90502 4. Generator's Phone (213) 533-6677 K. L. Anderson 722 M/S C6-10				H-A-H-Q-3-6-0-0-5-6-9-8					
Transporter 1 Company Name	C. State Transporter's ID 01392/ D. Transporter's Phone (213)269-3137								
I.C.I. Environmental Services Transporter 2 Company Name	E. State Transporter's ID F. Transporter's Phone								
Designated Facility Name and Site Address SPCI Lone Mountain Facility LS. Pollution Control, Inc. /R 2, Box 180A	10. US EPA ID Number			te Facility's ID	1.1	<u> </u>			
lavnoka, Ökl. 73860	<u> 10.1K.1D.10.16.15.14.13.18.</u>	3 7 G	ainers	(405)69 13. Total	14.	1.			
1. US DOT Description (Including Proper Shipping Name, Haza	ard Class, and ID Number)	No.	Туре	Quantity	Unit Wt/Vo	Waste No.			
Masta Sodium Hydroxide solution, (DOO2) (RQ 1,000 lbs.)	Corrosive, UN1824	0 0 11	TIT	0400	9 6	122 EPA/Other 0002 State			
		1 1	1	1 1 1 1		EPA/Other State			
		1.1		1111		EPA/Other			
			<u>_</u> 1	1111		State EPA/Other			
. Additional Descriptions for Materials Listed Above Daco 4-L Aluminum Milling Solution Sodium Hydroxide 5-12% Sod	K. Handling Codes for Wast a. b c. d								
Sodium Sulfide 2-4% Mat ISPCI ID# IMR9-0866-89 <u>Okt. Mas</u>	er = Remainder to Plan # 96021								
15. Special Handling Instructions and Additional Information Guide f 60. Use proper protective clothing when handeling. Return to MDC if rejected.	PROF HAUL	ILE #2 即 18	2417 134						
GENERATOR'S CERTIFICATION: I hereby declare that the and are classified, packed, marked, and labeled, and are national government regulations. If I am a large quantity generator, I certify that I have a provided to be economically practicable and that I have selected the present and future threat to human health and the environ generation and select the best waste management methological.	in all respects in proper condition to ogram in place to reduce the volum- ne practicable method of treatment, ment: OR. if I am a small quantity g	e and toxicil storage, or enerator, I I	y of wa	ste generated to	the degre	e I have determined which minimizes the inimize my waste			
Printed/Typed Name Kris L. Anderson Agent for M.D.A. 17. Transporter 1 Acknowledgement of Receipt of Materials	Signature	16	7			Month Day 0 2 2 7 9			
Printed/Typed Name CARLOS ROBRIGUEZ	S RODRIGUEZ Signature Cas Cos Xodrigues								
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature		-			Month Day			
19. Discrepancy Indication Space									
20. Facility Owner or Operator Certification of receipt of haza		nifest exce	pt as no	ted in Item 19.		Month Day			
Printed/Typed Name	Signature					мони рау			

DHS 8022 A (1/88) EPA 8700—22 (Rev. 9-88) Previous editions are obsolete.

IN CASE OF AN EMERGENCY OR SPILL, CALL THE NATIONAL ROUNSE CENTER 1-800-424-8802, WITHIN CALIFORNIA CALL 1-800-852-7550

Do Not Write Below This Line

YELLOW: GENERATOR RETAINS